

**Auxiliary Materials
Temperature Measuring**

Product	Firing Range	Porcelain	Bone China	Vitreous China	Earthenware	Glass	Notes
temperature measuring indicator	700-880°C 1290-1616°F	●	●	●	●		temperature measuring indicator for exact measurement of the firing temperature, easy to handle